

# PQ Systems Ltd.

- Motion Control -


## SSMSxxxP0

<b>Description</b>	Molded Heavy Duty cable for use with MTS Sensors with MS0 or FM_ option
<b>xxx</b>	Cable length in feet. (005=5ft, 015=15ft, 025=25ft, 050=50ft, 100=100ft)
<b>Cable</b>	Black Heavy Duty Polyurethane Jacket (ABC3959)
<b>Connector</b>	MS 10 Pin Female (MS3116F12-10S)

MS 10Pin	Color	G-Series S/S or PWM with MS0, FM1 or FM2 connector option	R-Series SSI with MS0 connector option
A	White	DC ground (for supply)	DC Ground (for supply)
B	-		-
C	Gray	(-) Gate for PWM (-) Stop for Start/Stop, or Programming (RS-422 TX -)	- Data
D	Pink	(+) Gate for PWM (+) Stop for Start/Stop, or Programming (RS-422 TX +)	+ Data
E	Red	Supply Voltage (+Vdc)	+ 24 VDC Supply Voltage
F			
G	Yellow	(+) Interrogation for PWM (external only) (+) Start for Start/Stop, or Programming (RS-422 RX +)	+ Clock
H	Green	(-) Interrogation for PWM (external only) (-) Start for Start/Stop, or Programming (RS-422 RX -)	- Clock
J			
K			



End of Cable



Solder Side